

# SAFETY RECALL NOTICE

## 2013 – 2016 Cannondale CAADX Cyclocross Bicycles

### Recalled Product:

All model year 2013 through 2016 Cannondale CAADX Cyclocross bicycles equipped with disc brakes.

### Hazard:

The fork can fracture, which can allow the wheel to detach from the bicycle during use, posing a fall hazard.

### Remedy:

Consumers should stop using the recalled bicycle and contact the nearest Cannondale dealer for a free repair. Cannondale dealers will replace, free of cost, the bicycle's fork with a full carbon fiber replacement fork.

### Identification:



These CAADX bicycles were sold in a variety of component specifications and colors. Consumers should inspect their bicycle to determine if it is affected by this recall by confirming:

1. The bicycle has a prominent “CAADX” marking on the top tube or other location.
2. The bicycle has disc brakes.
3. The inside of each fork leg has a large “ULTRAX” marking.
4. The cable connected to the front disc brake is completely outside the fork blade. Later models, not subject to recall, have the cable connected to the front disc brake routed internally, inside the structure of the fork blade.

For assistance determining if a bicycle is affected, bring it to a Cannondale authorized dealer.

To help you find your nearest dealer, please visit [www.cannondale.com/en/reat/ritain/dealers-near-you.asp](http://www.cannondale.com/en/reat/ritain/dealers-near-you.asp) or email [warranty\\_cyclingsportsgroup.co.uk](mailto:warranty_cyclingsportsgroup.co.uk)